

PRODUCT CHANGE NOTIFICATION

ID-No.: BLO-2016102801

DEAR SIR OR MADAM,

We would like to inform you about the following product change:

DESCRIPTION OF CHANGE

Modification of the enclosure, which allows lateral mounting by using an optional universal DIN rail adapter PC-TS35Z.

Depending on the device, there are two mounting possibilities for PC-TS35Z:

- 1.) Lateral mounting only on the right side
- 2.) Lateral mounting on both sides

REASON FOR CHANGE

Customer demand for the possibility of lateral mounting.



Current design



New design

Date of announcement	2016-10-28	
Scheduled date of change	Q4/16 – Q1/17	
Marking for change	Lateral holes in the housing	
Productgroup	PC-Series	
Parts affected	Lateral mounting only on the right side: PC-0324-400-0, PC-0324-0400-1, PC-0324-400-2, PC-0324-400-4, PC-0324-400-6, PC-0348-200-0, PC-0348-200-2, PC-0348-200-4, PC-0360-160-0, PC-0360-160-2, PC-0360-160-4, PC-0624-400-0, PC-0648-400-0 Lateral mounting on both sides: PC-0112-150-0, PC-0112-150-1, PC-0124-100-0, PC-0124-100-4, PC-0124-200-0, PC-0124-200-4, PC-0148-050-0, PC-0148-100-0, PC-0324-100-0, PC-0324-100-2, PC-0324-100-4, PC-0324-100-6, PC-0324-200-0, PC-0324-200-1, PC-0324-200-2, PC-0324-200-4, PC-0324-200-6	
Existing inventory still can be used	<input checked="" type="checkbox"/> yes	<input type="checkbox"/> no
Mixing of inventory approved	<input checked="" type="checkbox"/> yes	<input type="checkbox"/> no
Issued by	K. Heinemann Product Manager Electronic	

PRODUCT CHANGE NOTIFICATION

ID-No.: BLO-2016102801

DEAR SIR OR MADAM,

We would like to inform you about the following product change:

DESCRIPTION OF CHANGE

Modification of the enclosure, which allows lateral mounting by unscrewing the existing DIN rail adapter from the back of the device and moving it to the side or by using an optional universal DIN rail adapter PC-TS35Z.

REASON FOR CHANGE

Increased customer demand for the possibility of lateral mounting.



Current design



New design

Date of announcement	2016-10-28	
Scheduled date of change	Q4/16 – Q1/17	
Marking for change	Lateral holes in the housing	
Product group	PC-Series	
Parts affected	PC-0124-050-0, PC-0124-050-4, PC-0224-050-0, PC-0224-050-2, PC-0224-100-0, PC-0224-100-2, PC-0724-480-0, PC-0724-480-2, PC-0724-800-0, PC-0724-800-1, PC-0724-800-2, PC-0748-800-0, PC-0748-800-2, PC-0824-480-0, PC-0824-480-1, PC-1024-050-0, PC-1824-480-0, PC-3724-800-0	
Existing inventory still can be used	<input checked="" type="checkbox"/> yes	<input type="checkbox"/> no
Mixing of inventory approved	<input checked="" type="checkbox"/> yes	<input type="checkbox"/> no
Issued by	K. Heinemann Product Manager Electronic	